



DEPARTMENT OF THE NAVY
COMMANDER, FLEET ACTIVITIES YOKOSUKA
PSC 473 BOX 1
FPO AP 96349

5090
Ser N00/0379
3 Mar 25

From: Commander, Fleet Activities Yokosuka
To: Parents and Staff

Subj: IKEGO CHILD DEVELOPMENT CENTER'S DRINKING WATER

Enc1: (1) Sample Summary Results Table
(2) Floor Plan - Ikego Child Development Center

1. I want to make you aware of the latest developments regarding our efforts to address elevated lead levels in drinking water testing that was completed in May 2022 at Fleet Activities (FLEACT) Yokosuka Ikego Child Development Center (CDC).

2. On 16 January 2025, the community was made aware of the water testing results from 54 outlets. Of these outlets two require action due to results above the updated Navy screening level of 10 ppb for lead. Fixtures that had results at or above 10 ppb were taken out of service.

3. We recently completed all corrective measures, and additional testing show that the lead levels at Ikego CDC are all below 10 ppb.

4. I've attached the complete set of test results, which include the list of sampling locations and the purpose of the water outlet (drinking fountain or sink). As described above, for those locations that exceeded the recommended screening level on the first test, we conducted follow-on resampling. The attachment provides details on which outlets required corrective action and the actions taken. For outlets where corrective actions were implemented, the attachment also shows the results of follow-on sampling to confirm that lead levels were below 10 ppb. I've also enclosed a floor plan which delineates locations where initial water sampling results exceeded 10 ppb. All outlets are now below the screening level.

5. For your information, I am also including links to additional drinking water quality resources:

a. Environmental Protection Agency (EPA) (lead in drinking water in schools and childcare centers): <https://www.epa.gov/ground-water-and-drinking-water/basic-information-about-lead-drinking-water>

b. Annual consumer confidence water quality report for the installation:
<https://cnrj.cnmc.navy.mil/Operations-and-Management/Water-Quality-Information/Water-quality-reports/#CFAY>

6. Please be assured that my team and I will continue to monitor and test water quality at FLEACT, Yokosuka Ikego CDC to ensure our drinking water complies with EPA regulations. If you have questions or concerns, please bring them to the attention of the staff.

Subj: IKEGO CHILD DEVELOPMENT CENTER'S DRINKING WATER

7. If you have any health questions or concerns, I encourage you to contact your health care provider or, if you are a TRICARE beneficiary, use the Yokosuka Naval Hospital Appointment Center to schedule an appointment with your primary care provider at (315) 243-5352.

8. I am committed to the safety and health of all personnel and family members using our facilities and will keep you updated on this issue.



L. D. SOBOL

Copy to:
CNIC N45
NAVFAC Environmental (EV)

Sample Summary Results Table

Priority Areas Lead Testing and Corrective Actions

FLEACT Yokosuka - Ikego Child Development Center

Table 1. Summary of Results-Ikego Child Development Center Bldg. 673

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST-CORRECTIVE ACTION SAMPLING RESULTS	
CATEGORY	SAMPLE ID	Sample Location	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Sealed? (See Note 2)	First Draw (ppb)	Follow up Flush (ppb) - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See Note 3)	Recommended Level = 10 ppb	
SAMPLING DATE RESULTS DATE				5/12/2022		N/A	N/A	30	N/A	N/A	N/A	
DRINKING	IK6573B007	Preschooler Room #1	Bubbler	N/A	NO		N/A					
	IK6573B012	Preschooler Room #2	Bubbler	15	YES	6/16/2022	14	Sample date: 6/17/2022 Results date: 6/23/2022	Outlet was replaced.	Sample date: 8/12/2022 Results date: 8/12/2022	4.1	
	IK6573B017	Preschooler Room #3	Bubbler	3.9	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573B022	Toddler Room #1	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573B027	Toddler Room #2	Bubbler	1.1	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573B032	Preschool Room #1	Bubbler	1.9	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573B062	Preschool Room #2	Bubbler	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C045	Lobby	Goosier	9.1	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C046	Lobby	Goosier	0.9	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C050	Kitchen	Faucet	4.6	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C051	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C052	Kitchen	Faucet	0.91	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C053	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C054	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C055	Kitchen	Faucet	0.56	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C056	Kitchen	Faucet	6.7	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C057	Infant Room #1 & Reception	Faucet	0.5	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IK6573C058	Infant Room #1 & Reception	Faucet	0.81	NO	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C059	Infant Room #1 & Reception	Faucet	1.8	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C062	Infant Room #1 & Reception	Faucet	1.7	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C064	Infant Room #2	Faucet	2.6	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C066	Infant Room #2	Faucet	4.3	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C068	Preschooler Room #1	Faucet	2.3	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C069	Preschooler Room #1	Faucet	5.7	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C070	Preschooler Room #1	Faucet	2.6	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C071	Preschooler Room #1	Faucet	5.4	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C073	Preschooler Room #2	Faucet	0.71	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C074	Preschooler Room #2	Faucet	1.6	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C075	Preschooler Room #2	Faucet	3.1	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C076	Preschooler Room #2	Faucet	2.5	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C077	Preschooler Room #3	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C078	Preschooler Room #3	Faucet	0.85	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C021	Preschooler Room #3	Faucet	4.2	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C023	Toddler Room #1	Faucet	0.75	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C024	Toddler Room #1	Faucet	0.58	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C025	Toddler Room #1	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C026	Toddler Room #1	Faucet	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C028	Toddler Room #2	Faucet	3.9	NO	N/A	N/A	N/A	N/A	N/A	N/A		
IK6573C029	Toddler Room #2	Faucet	14	YES	7/30/2024	N/A	N/A	N/A	Outlet was replaced.	Sample date: 2/13/2025 Results date: 2/21/2025	3.7	
IK6573C030	Toddler Room #2	Faucet	4.7	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C031	Toddler Room #2	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C032	Toddler Room #2	Faucet	3.8	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C033	Preschool Room #1	Faucet	0.66	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C034	Preschool Room #1	Faucet	0.86	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C035	Preschool Room #1	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C036	Preschool Room #1	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C037	Preschool Room #1	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C038	Preschool Room #2	Faucet	5.1	NO	N/A	N/A	N/A	N/A	Outlet was replaced.	Sample date: 2/13/2025 Results date: 2/21/2025	2.7	
IK6573C039	Preschool Room #2	Faucet	11	YES	7/30/2024	N/A	N/A	N/A	Outlet was replaced.	Sample date: 2/13/2025 Results date: 2/21/2025	6.3	
IK6573C040	Preschool Room #2	Faucet	1	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C042	Toilet (next to Multi Purpose RM)	Faucet	1.4	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C043	Toilet (next to Multi Purpose RM)	Faucet	1.4	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C044	Toilet (next to Multi Purpose RM)	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IK6573C047	Staff Room	Faucet	0.89	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

Notes: In July 2024, Commander, Navy Installation Command (CNIC) Instruction 5006(A) lowered the lead screening level at all Priority Areas from 15 parts per billion (ppb) to 10 ppb.

¹ Affected outlets were re-sampled, corrective actions, and post-corrective actions were completed in 2022 and 2025 to meet the lead screening level of 15 ppb and 10 ppb, respectively.

² Results are below screening level of 10 ppb. No additional actions required.

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS				RE-SAMPLING RESULTS				POST-CORRECTIVE ACTION RESULTS			
	Lead Screening Level of 10 ppb (See note 1)				Lead Screening Level of 10 ppb (See note 1)				Follow up Flush			
	First Draw (ppb)	Water Fountain	First Draw (ppb)	Follow up Flush	First Draw (ppb)	Water Fountain	First Draw (ppb)	Follow up Flush	First Draw (ppb)	Water Fountain	First Draw (ppb)	Follow up Flush
Total Drinking	9	0	1	1	1	0	1	1	1	0	1	1
Total Drinking > 10 ppb	1	0	1	1	1	0	1	1	1	0	1	1
Total Cook	7	0	0	0	0	0	0	0	0	0	0	0
Total Cook > 10 ppb	0	0	0	0	0	0	0	0	0	0	0	0
Total Washing	38	0	0	0	0	0	0	0	0	0	0	0
Total Washing > 10 ppb	0	0	0	0	0	0	0	0	0	0	0	0
Total Sampling	64	0	1	1	1	0	1	1	1	0	1	1
Total Sampling > 10 ppb	3	0	1	1	1	0	1	1	1	0	1	1

**Floor Plan - Ikego Child Development Center
Bldg. 673 - 2024 Replacements**

F = Faucet
C = Cooler water fountain
B = Bubbler water fountain

