



DEPARTMENT OF THE NAVY
COMMANDER, FLEET ACTIVITIES YOKOSUKA
PSC 473 BOX 1
FPO AP 96349

11330
Ser N00/0770
19 May 25

From: Commander, Fleet Activities Yokosuka
To: Parents and Staff

Subj: IKEGO ELEMENTARY SCHOOL'S DRINKING WATER

Enc1: (1) Sample Summary Results Table
(2) Floor Plan - Ikego Elementary School

1. I want to make you aware of the latest developments regarding our efforts to address elevated lead levels in drinking water testing that was completed in May 2022 at Fleet Activities (FLEACT) Yokosuka Ikego Elementary School.

2. On 16 January 2025, the community was made aware of the water testing results from 253 outlets. Of these outlets five require action due to results above the updated Navy screening level of 10 ppb for lead. Fixtures that had results at or above 10 ppb were taken out of service.

3. We recently completed all corrective measures, and additional testing show that the lead levels at Ikego Elementary School are all below 10 ppb.

4. I've attached the complete set of test results, which include the list of sampling locations and the purpose of the water outlet (drinking fountain or sink). As described above, for those locations that exceeded the recommended screening level on the first test, we conducted follow-on resampling. The attachment provides details on which outlets required corrective action and the actions taken. For outlets where corrective actions were implemented, the attachment also shows the results of follow-on sampling to confirm that lead levels were below 10 ppb. I've also enclosed a floor plan which delineates locations where initial water sampling results exceeded 10 ppb. All outlets are now below the screening level.

5. For your information, I am also including links to additional drinking water quality resources:

a. Environmental Protection Agency (EPA) (lead in drinking water in schools and childcare centers): <https://www.epa.gov/ground-water-and-drinking-water/basic-information-about-lead-drinking-water>

b. Annual consumer confidence water quality report for the installation:
<https://cnrj.cnmc.navy.mil/Operations-and-Management/Water-Quality-Information/Water-quality-reports/#CFAY>

Subj: IKEGO ELEMENTARY SCHOOL'S DRINKING WATER

6. Please be assured that my team and I will continue to monitor and test water quality at FLEACT Yokosuka Ikego Elementary School to ensure our drinking water complies with EPA regulations. If you have questions or concerns, please bring them to the attention of the staff.
7. If you have any health questions or concerns, I encourage you to contact your health care provider or, if you are a TRICARE beneficiary, use the Yokosuka Naval Hospital Appointment Center to schedule an appointment with your primary care provider at (315) 243-5352.
8. I am committed to the safety and health of all personnel and family members using our facilities and will keep you updated on this issue.



L. D. SOBOL

Copy to:
CNIC N45
NAVFAC Environmental

Sample Summary Results Table

Priority Areas Lead Testing and Corrective Actions

FLEACT Yokosuka - Ikego Elementary School

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS		CORRECTIVE ACTIONS	POST-CORRECTIVE ACTION SAMPLING RESULTS			
CATEGORY	SAMPLE ID	Room Number	Outlet Location	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 2)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 3)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
SAMPLING DATE	RESULTS DATE												
DRINKING	IKES24C002-B	101	Hallway	Cooler	Non-Detect	NO	N/A	6/22/2022	6/22/2022	N/A	N/A	N/A	
	IKES24C003-A	103	Hallway	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IKES24C003-B	103	Hallway	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IKES24C004-A	103	Hallway	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IKES24C004-B	103	Hallway	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IKES24C006-A	104	Hallway	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IKES24C006-B	104	Hallway	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	
	IKES24B014	119	Break room / Work room	Bubbler	0.9	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B015	126		Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B017	130		Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B023	144		Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B027	148		Bubbler	0.86	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B032	153	Infant room 3	Bubbler	0.58	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B035	156	Infant room 4	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B038	159	Infant room 5	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B041	162	Care Room	Bubbler	19	YES	6/16/2022	18	Non-Detect	Outlet and supply piping components were replaced with Lead free material.	1.1	Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022	Non-Detect
	IKES24B044	165	Classroom 1	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B045	166	Classroom 2	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	IKES24B046	167	Classroom 3	Bubbler	0.7	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A
IKES24B047	168	Classroom 4	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B048	169	Classroom 5	Bubbler	2.7	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B049	171	Classroom 9	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B050	173	Art room	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B051	173	Art room	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B053	177	Music room	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B054	179	Work room	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C066-B	201	Corridor 1	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C067-A	201	Corridor 1	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C067-B	201	Corridor 1	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C068-B	203	Corridor 3	Cooler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C069	203	Corridor 3	Cooler	0.88	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B077	218	Classroom 1	Bubbler	1.8	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B078	219	Classroom 2	Bubbler	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B079	220	Classroom 3	Bubbler	0.71	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B080	221	Classroom 4	Bubbler	1.1	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B081	222	Classroom 5	Bubbler	2.8	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B082	223	Classroom 6	Bubbler	4.1	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B083	224	Classroom 7	Bubbler	4.5	NO	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B084	225	Recess Room	Bubbler	35	YES	6/16/2022		25	3.4	Outlet and supply piping components were replaced with Lead free material.	4.5	Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022	
IKES24B085	226	Work room	Bubbler	12	YES	7/30/2024		N/A	N/A	Outlet was replaced with Lead free material	1.2	Sample date: 4/15/2025 Results date: 4/25/2025	
IKES24B087	232	Classroom	Bubbler	1.3	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B088	233	Classroom	Bubbler	10	YES	7/30/2024		N/A	N/A	Outlet was replaced with Lead free material.	5.5	Sample date: 4/15/2025 Results date: 4/25/2025	
IKES24B089	234	Classroom	Bubbler	13	YES	7/30/2024		N/A	N/A	Outlet was replaced with Lead free material.	7.5	Sample date: 4/15/2025 Results date: 4/25/2025	
IKES24B090	235	Classroom	Bubbler	9.8	YES	7/30/2024		N/A	N/A	Outlet was replaced with Lead free material.	9.3	Sample date: 4/15/2025 Results date: 4/25/2025	
IKES24B091	236	Classroom	Bubbler	3.9	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B093	244	Classroom 8	Bubbler	Non-Detect	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24B094	249	Classroom	Bubbler	2.4	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C102-A	257	Lunch room	Cooler	Non-Detect	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C102-B	257	Lunch room	Cooler	Non-Detect	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C108-A	261	Gym	Cooler	Non-Detect	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C108-B	261	Gym	Cooler	Non-Detect	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C113-A	301	Corridor 1	Cooler	Non-Detect	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C113-B	301	Corridor 1	Cooler	Non-Detect	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C115	302	Corridor 2	Cooler	0.93	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C116-A	303	Corridor 3	Cooler	Non-Detect	NO		N/A	N/A	N/A	N/A	N/A	N/A	
IKES24C116-B	303	Corridor 3	Cooler	Non-Detect	NO		N/A	N/A	N/A	N/A	N/A	N/A	

Sample Summary Results Table

Priority Areas Lead Testing and Corrective Actions

FLEACT Yokosuka - Ikego Elementary School

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS				RE-SAMPLING RESULTS		CORRECTIVE ACTIONS	POST-CORRECTIVE ACTION SAMPLING RESULTS	
CATEGORY	SAMPLE ID	Room Number	Outlet Location	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 2)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 3)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE RESULTS DATE					5/17/2022-5/25/2022 6/15/2022			6/22/2022 7/1/2022	6/22/2022 7/1/2022			
DRINKING	IKES248126	320	Classroom 1	Bubbler	2.3	NO	N/A	N/A	N/A	Connected to exceeding outlet. Replaced supply piping components with Lead free material.	0.5 Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022	Non-Detect Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022
DRINKING	IKES248127	321	Classroom 2	Bubbler	0.67	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248128	322	Classroom 3	Bubbler	0.65	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248129	323	Classroom 4 (3 grade)	Bubbler	1.4	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248130	324	Classroom 4 (4 grade)	Bubbler	1.2	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248131	325	Classroom 5	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248132	326	Classroom 1	Bubbler	0.61	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248133	327	Classroom 2	Bubbler	1.7	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248134	328	Classroom 3	Bubbler	0.53	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248135	329	Classroom 5 (4 grade)	Bubbler	7.1	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248136	330	Classroom 5 (5 grade)	Bubbler	0.59	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248137	333	Classroom 6	Bubbler	0.73	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248139	336	Classroom 1	Bubbler	3.3	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248140	337	Classroom 2	Bubbler	1.7	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248141	338	Classroom 3	Bubbler	1.1	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248142	339	Classroom 4	Bubbler	0.61	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248021	139a	Classroom 7	Bubbler	2.7	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248022	139b	Classroom 8	Bubbler	1.4	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24C002-A	NA	Hallway	Cooler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24C005	NA	Hallway	Cooler	0.71	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24C066-A	NA	Corridor 1	Cooler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24C068-A	NA	Corridor 3	Cooler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24C112	NA	Corridor 1	Cooler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24C114	NA	Corridor 2	Cooler	0.6	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248143	North	Outside	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248144	North	Outside	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248148	North	Outside	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248149	North	Outside	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248150	North	Outside	Bubbler	0.56	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248151	North	Outside	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24C178	North	Outside	Cooler	2.1	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24C179-A	North	Outside	Cooler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24C179-B	North	Outside	Cooler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248163	South	Outside	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248164	South	Outside	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248167	South	Outside	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES248168	South	Outside	Bubbler	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24F161	South	Outside	Bubbler	0.76	NO	N/A	N/A	N/A		N/A	N/A
DRINKING	IKES24F162	South	Outside	Bubbler	0.67	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F016	126	Break room / Work room	Faucet	0.89	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F025	145	Admin / Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F028	149	Admin / Kitchen 2	Faucet	0.63	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F033	154	Admin / Kitchen 3	Faucet	0.51	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F036	157	Admin / Kitchen 4	Faucet	0.64	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F039	160	Admin / Kitchen 5	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F042	163	Kitchen	Faucet	6.5	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F055	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F056	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F057	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F058	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F059	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F061	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F062	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F063	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F299	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F301	181	Kitchen	Faucet	0.7	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F302	181	Kitchen	Faucet	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F096	231	Food prep/lecture area	Faucet	0.96	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F092	243	Preparation room / Kitchen	Faucet	0.73	NO	N/A	N/A	N/A		N/A	N/A
COOKING	IKES24F138	335	Break room	Faucet	0.75	NO	N/A	N/A	N/A		N/A	N/A
WASHING	IKES24F187	109	Bathroom	MSF	3.2	NO	N/A	N/A	N/A		N/A	N/A
WASHING	IKES24F188	110	Bathroom	MSF	2.4	NO	N/A	N/A	N/A		N/A	N/A
WASHING	IKES24F197	113	Boys Bathroom	MSF	1.2	NO	N/A	N/A	N/A		N/A	N/A
WASHING	IKES24F198	113	Boys Bathroom	MSF	2.6	NO	N/A	N/A	N/A		N/A	N/A
WASHING	IKES24F199	113	Boys Bathroom	MSF	2.3	NO	N/A	N/A	N/A		N/A	N/A
WASHING	IKES24F200	113	Boys Bathroom	MSF	0.67	NO	N/A	N/A	N/A		N/A	N/A
WASHING	IKES24F201	114	Girls Bathroom	MSF	Non-Detect	NO	N/A	N/A	N/A		N/A	N/A
WASHING	IKES24F202	114	Girls Bathroom	MSF	1.5	NO	N/A	N/A	N/A		N/A	N/A

Sample Summary Results Table
Priority Areas Lead Testing and Corrective Actions
FLEACT Yokosuka - Ikego Elementary School

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS		CORRECTIVE ACTIONS		POST-CORRECTIVE ACTION SAMPLING RESULTS	
CATEGORY	SAMPLE ID	Room Number	Outlet Location	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (see Note 2)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (see note 3)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE RESULTS DATE					5/17/2022-5/25/2022			6/22/2022	6/22/2022			
					6/15/2022			7/1/2022	7/1/2022			
WASHING	IKER24F203	114	Girls Bathroom	MSF	1.5	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F204	114	Girls Bathroom	MSF	0.78	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F012	117	Women Staff Bathroom	MSF	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F013	118	Men Staff Bathroom	MSF	0.67	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F207	119	Classroom 6	MSF	1.1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F018	130	Nurse Office	Faucet	0.64	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F019	131	Shower room in Nurse Office	MSF	1.9	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F190	144	Infant room 1	MSF	0.67	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F191	144	Infant room 1	MSF	0.74	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F192	144	Infant room 1	MSF	0.62	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F026	146	Boys Girls Juvenility Bathroom	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F183	146	Boys Girls Juvenility Bathroom	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F193	148	Infant room 2	MSF	0.64	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F194	148	Infant room 2	MSF	0.94	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F195	148	Infant room 2	MSF	1.1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F029	150	Juvenile bath room	MSF	2.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F208	153	Infant room 3	MSF	1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F209	153	Infant room 3	MSF	1.3	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F210	153	Infant room 3	MSF	1.7	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F034	155	Boys Girls Juvenility Bathroom	MSF	1.1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F184	155	Boys Girls Juvenility Bathroom	MSF	1.3	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F211	156	Infant room 4	MSF	3.3	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F212	156	Infant room 4	MSF	1.9	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F213	156	Infant room 4	MSF	1.6	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F037	158	Boys Girls Juvenility Bathroom	MSF	0.7	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F185	158	Boys Girls Juvenility Bathroom	MSF	0.94	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F214	159	Infant room 5	MSF	1.7	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F215	159	Infant room 5	MSF	2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F216	159	Infant room 5	MSF	2.5	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F040	161	Boys Girls Juvenility Bathroom	MSF	2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F186	161	Boys Girls Juvenility Bathroom	MSF	0.87	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F222	162	Care Room	MSF	5.5	NO	N/A	N/A	N/A	Connected to exceeding outlet. Replaced outlet and supply piping components with Lead free material.	Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022	Non-Detect
WASHING	IKER24F223	162	Care Room	MSF	29	YES	6/16/2022	33	5.8	Outlet and supply piping components were replaced with Lead free material.	Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022	Non-Detect
WASHING	IKER24F224	162	Care Room	MSF	48	YES	6/16/2022	19	2	Outlet and supply piping components were replaced with Lead free material.	Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022	Non-Detect
WASHING	IKER24F043	164	Boys Girls Juvenility Bathroom	MSF	3	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F298	164	Boys Girls Juvenility Bathroom	MSF	4.9	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F217	165	Classroom 1	MSF	3	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F218	166	Classroom 2	MSF	0.57	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F297	167	Classroom 3	MSF	0.83	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F219	168	Classroom 4	MSF	0.56	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F220	169	Classroom 5	MSF	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F221	171	Classroom 9	MSF	0.8	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F225	173	Art room	MSF	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F226	173	Art room	MSF	1.5	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F227	173	Art room	MSF	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F228	173	Art room	MSF	1.8	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F229	173	Art room	MSF	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F230	173	Art room	MSF	1.6	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F300	176	Art room	MSF	4.6	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F231	177	Musik room	MSF	1.6	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F232	179	Work room	Faucet	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F233	181	Kitchen	MSF	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F303	181	Kitchen	Faucet	26	YES	6/16/2022	8.5	1.6	Outlet was replaced with Lead free material.	Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022	0.8
WASHING	IKER24F065	183	Bathroom	MSF	0.67	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F070	209	Male Bathroom	MSF	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F071	210	Female Bathroom	MSF	0.72	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F246	213	Boys Bathroom	MSF	0.84	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F247	213	Boys Bathroom	MSF	0.59	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F248	213	Boys Bathroom	MSF	0.61	NO	N/A	N/A	N/A	N/A	N/A	N/A

Sample Summary Results Table
Priority Areas Lead Testing and Corrective Actions
FLEACT Yokosuka - Ikego Elementary School

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS		CORRECTIVE ACTIONS		POST-CORRECTIVE ACTION SAMPLING RESULTS	
CATEGORY	SAMPLE ID	Room Number	Outlet Location	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (see Note 2)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (see note 3)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE RESULTS DATE					5/17/2022-5/25/2022			6/22/2022	6/22/2022			
					6/15/2022			7/1/2022	7/1/2022			
WASHING	IKER24F249	213	Boys Bathroom	MSF	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F250	214	Girls Bathroom	MSF	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F251	214	Girls Bathroom	MSF	2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F252	214	Girls Bathroom	MSF	0.73	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F253	214	Girls Bathroom	MSF	0.65	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F075	216	Female Bathroom	MSF	0.76	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F076	217	Male Bathroom	MSF	1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F254	218	Classroom 1	MSF	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F255	219	Classroom 2	MSF	0.67	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F257	220	Classroom 3	MSF	0.59	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F258	221	Classroom 4	MSF	6.8	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F234	222	Classroom 5	MSF	4.4	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F259	223	Classroom 6	MSF	2.9	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F260	224	Classroom 7	MSF	1.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F261	225	Science room	MSF	1.1	NO	N/A	N/A	N/A	Connected to exceeding outlet. Replaced outlet and supply piping components with Lead free material.	4.4	2
										Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022		2
WASHING	IKER24F262	226	Work room	MSF	13	YES	7/30/2024	N/A	N/A	Outlet was replaced with Lead free material.	2	0.7
										Sample date: 4/15/2025 Results date: 4/29/2025		
WASHING	IKER24F235	232	Classroom	MSF	2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F236	233	Classroom	MSF	1.7	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F237	234	Classroom	MSF	1.4	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F238	235	Classroom	MSF	1.1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F239	236	Classroom	MSF	2.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F256	244	Classroom 8	MSF	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F260	249	Classroom 2	MSF	2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F261	250	Boys Bathroom	MSF	4	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F262	250	Boys Bathroom	MSF	1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F263	251	Girls Bathroom	MSF	1.7	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F264	251	Girls Bathroom	MSF	2.5	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F265	251	Girls Bathroom	MSF	1.7	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F263	253	Boys Bathroom	MSF	0.8	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F264	253	Girls Bathroom	MSF	0.53	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F111	264	Bathroom	MSF	1.6	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F265	310	Boys Bathroom	MSF	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F266	310	Boys Bathroom	MSF	0.72	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F267	311	Girls Bathroom	MSF	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F268	311	Girls Bathroom	MSF	1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F269	311	Girls Bathroom	MSF	4.1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F275	314	Boys Bathroom	MSF	0.56	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F276	314	Boys Bathroom	MSF	1.1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F277	314	Boys Bathroom	MSF	0.79	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F278	315	Boys Bathroom	MSF	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F279	315	Girls Bathroom	MSF	0.85	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F280	315	Girls Bathroom	MSF	0.58	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F281	315	Girls Bathroom	MSF	1.1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F282	315	Girls Bathroom	MSF	0.74	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F124	318	Female Bathroom	MSF	0.71	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F125	319	Male Bathroom	MSF	1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F283	320	Classroom 1	MSF	15	NO	6/16/2022	17	1.2	Outlet and supply piping components were replaced with Lead free material.	1.7	0.5
										Sample date: 8/3/2022-10/8/2022 Results date: 10/18/2022		
WASHING	IKER24F284	321	Classroom 2	MSF	1.7	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F286	322	Classroom 3	MSF	0.66	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F287	323	Classroom 4 (3 grade)	MSF	5.6	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F288	324	Classroom 4 (4 grade)	MSF	1.3	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F285	325	Classroom 5	MSF	2.1	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F289	326	Classroom 1	MSF	1.9	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F291	327	Classroom 2	MSF	0.85	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F292	328	Classroom 3	MSF	0.8	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F270	329	Classroom 5 (4 grade)	MSF	7.7	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F290	330	Classroom 5 (5 grade)	MSF	1.4	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F293	333	Classroom 6	MSF	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F271	336	Classroom 2	MSF	3.4	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F273	337	Classroom 3	MSF	2.2	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F274	338	Classroom 3	MSF	8	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F272	339	Classroom 4	MSF	5.9	NO	N/A	N/A	N/A	N/A	N/A	N/A
WASHING	IKER24F269	139a	Classroom 7	MSF		NO	N/A	N/A	N/A	N/A	N/A	N/A

Sample Summary Results Table

Priority Areas Lead Testing and Corrective Actions

FLEACT Yokosuka - Ikego Elementary School

SAMPLING LOCATION DESCRIPTION				INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS		CORRECTIVE ACTIONS		POST-CORRECTIVE ACTION SAMPLING RESULTS	
CATEGORY	SAMPLE ID	Room Number	Outlet Location	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (see Note 2)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 3)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE RESULTS DATE											
WASHING	IKE824F296	139b	Classroom 8	MSF	5/17/2022-5/25/2022			6/22/2022	6/22/2022		
WASHING	IKE824F103	259/260	Dish room	MSF	6/15/2022	NO	N/A	7/1/2022	7/1/2022	N/A	N/A
WASHING	IKE824F104	259/260	Dish room	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A
WASHING	IKE824F105	259/260	Dish room	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A
WASHING	IKE824F106	259/260	Dish room	Faucet	Non-Detect	NO	N/A	N/A	N/A	N/A	N/A
WASHING	IKE824F294	Outside	Pavilion Bathroom Men	MSF	3	NO	N/A	N/A	N/A	N/A	N/A
WASHING	IKE824F295	Outside	Pavilion Bathroom Women	MSF	0.54	NO	N/A	N/A	N/A	N/A	N/A

Notes:
¹ In July 2024, Commander, Navy Installations Command (CNIC) Instruction 5090.6A lowered the lead screening level at all Priority Areas from 15 parts per billion (ppb) to 10 ppb.
² Affected outlets were secured, corrective actions, and post corrective actions were completed in 2022 and 2025 to meet the lead screening level of 15 ppb and 10 ppb, respectively.
³ Results are below screening level of 10 ppb. No additional actions required.

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS		POST-CORRECTIVE ACTION RESULTS	
	Lead Screening Level of 10 ppb (see note 1)		Lead Screening Level of 10 ppb (see note 1)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
	First Draw (ppb)	Water Fountain (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)	
Total Drinking	95	0	2	2	7	
Total Drinking > 10 ppb	5	0	2	0	0	
Total Cook	21	0	0	0	0	
Total Cook > 10 ppb	0	0	0	0	0	
Total Washing	137	0	4	4	7	
Total Washing > 10 ppb	5	0	3	0	0	
Total Samples	253	0	6	6	14	
Total Samples > 10ppb	10	0	5	0	0	

Floor Plan - Ikego Elementary School Bldg. 824 - 2024 Replacements

F = Faucet

C = Cooler water fountain

B = Bubbler water fountain

No Sampling at the following:

S = Shower

J = Janitor sink

HB = Hose Bibb

L = Lab Sink

